COBA

OBY VAO SEBO VEDO

3 September 1963

REPLY TO

ATTN OF: P.E.

SUBJECT: Monthly Activities Report for the Month of August 1963

TO: Commander WRSP-IV

1. Flight Discrepancies: There were no personal equipment discrepancies noted throughout the reporting period.

2. Leaves: took a five (5) day leave from 5 August to 9

STATINTL

August 1963.

3. Personnel:

nnounced his desires to terminate his tour with the organization

upon completion of the four (4) years minimum time. He desires to leave

a month earlier (August 1964) if possible in order to establish his

STATINTL

family before they start the 1964 school year.

nance

4. Seat Pack Maintenance: In addition to routine maintenance serviced five (5) ARDC and two (2) LAC seat packs.

5. Equipment and Materiel:

- entered forcedly by persons unknown by tearing the hinges from the door.

 The incident was noticed on the 28th of August and reported immediately to the Security Office for further action. There is no apparent evidence of pilfering but an inventory of the personal equipment account will have to be accomplished for verification.
- b. Transfer Vehicle: A jeep ambulance from the Barstow salvage
 yard is expected sometime during the month of September 1963, for use as
 Approved For Release 2002/06/24: CIA-RDP75B00326R000200100020-1

STATINTL

STATINTL

File

Approved For Release 2002/06/24 : CIA-RDP75B00326R000200100020-1

1		
i	a combination staging transfer vehicle and ambulance. The vehicle	
:	will be modified and furnished with air conditioning prior to being	STATINTL
	utilized as a transfer vehicle.	SIAIINIL
	c. Partial Pressure Suits: A reconditioned suit for	
	was found on trial fittings to be too small. has been	STATINTL
· ·	plaguad with suit problems since his arrival in the organization. He	İ
1	departed on 28 August for David Clark Company for on the spot fitting	
	and alterations to all three (3) suits issued to him. Additional suits	
STATINTL	for were received on 29 August and will be	
:	fitted to them as soon as their schedule permits.	STATINTL
	has indicated a tentative proposal on the part of IAC to allow mixe.	,
	cracks and crazing in certain areas of the Q336 faceplate in order to	
	temporarily relieve the demand for this item in the field. This organ-	
	ication has expressed disatisfaction with this proposal and does with	
	concur with it's applicability to our operation.	STATINTL
STATINTL	and his partial pressure suits	ILLEGIB
;	on requisition. Headquarters has advised expiditious actions	
STATINTL	half of David Clark. The first suit is a setted in the co	
STATINIL	October. He is currently wearing the old number 3 suit	
	and formerly the primary suit of	STATINTL
!	of Chippewa boot have been obtained for	STATINTL
,	d. Reasearch and Development: of Headquarters vis	it-
	ed the organization with a new seat pack and specialized parachute with	
	installed oxygen components. Presentation of the seat pack and para-	
;	2	

Approved For Release 2002/06/24: CIA-RDP75B00326R000200100020-1

STATINT

STATINTL

1	**************************************
	•
1	
1	

	* ************************************	
STATINTL	chute revealed they were not compatable with the requirements of this	
STATINTL	organization.	
STATINTL	net with pf IAC and	_
	and reviewed the Q445 seat pack. Plans are under way	ı
	to manufacture a prototype to our specifications. A tentative delive	гу
	date of the prototype could not be established at that time. The Q44	5
•	seat pack was favorably accepted by all attending the meeting with a	
, ,	few minor modifications to be made such as the height, tilt, seat qui	ck
,	disconnect, "beefed up" hardware, etc.	
STATINTL		

NCOIC Personal Equipment

3 Approved For Release 2002/06/24 : CIA-RDP75B00326R000200100020-1